

FEB 09 1982



OXY METAL INDUSTRIES CORPORATION

32100 STEPHENSON HWY., MADISON HEIGHTS, MICHIGAN 48071 (313) 583-9300

DPM 492

Lubricant, Compound
Extrusion

August 17, 1977

Douglas Aircraft Company
3855 Lakewood Boulevard
Long Beach, CA 90846

Attention: Mr. M. J. Veneroso

Dear Mr. Veneroso:

Your letter of May 23, 1977, addressed to our Buena Park facility was forwarded to the writer. Unfortunately, it arrived while I was out due to illness and has been buried with other work awaiting the time that I could catch up with it.

The questions concerning Oxyvate 301 B-30 will be handled by Mr. Winkler of the Udylite Division.

The remaining items are not listed by the DOT in section 172101 CFR-49 and do not meet the definitions for hazardous materials.

None of these items have a flash point.

The items referred to are:

Accelerator, 170
Accelerator, 171
Neutralizer, 270
Parco® Cleaner 342

Neutralizer 201
Parcolene® Neutralizer 21
Bonderlube® 239

DPM 2988
DPM 2988-1
DPM 2989
DPM 2990

DPM 3176

DPM 3176-1

DPM 5492

Although the information presented herein is to the best of our knowledge true and accurate, no warranty or guarantee, express or implied, is made regarding the information or the performance of any product. We assume no liability for incidental, consequential or direct damages of any kind, no matter what the cause, including negligence. Nothing contained herein shall be construed as a recommendation to use a product in infringement of any existing patent, and we assume no responsibility or liability for operations which do infringe any such patents. The above includes confidential and proprietary information of Oxy Metal Industries Corporation, and is furnished to you for your use solely on products or processes supplied by us to you.

BOE-C6-0202930


August 17, 1977

There is one peculiarity in the above products, and that has to do with Accelerator, 170. This product is sodium bifluoride. This product is not rated as a hazardous product by DOT for shipment within this country either by surface or by truck, however, the IATA does list it as a Poison B with an IATA number 2208.

If there are any further questions, please contact the writer.

Yours truly,

PARKER DIVISION
OXY METAL INDUSTRIES CORPORATION



W. R. Cavanagh, Manager
Technical Services

WRC:so